

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024
TUNING FORK SERIAL NUMBER 020028 WAS TESTED
AND FOUND TO OSCILLATE AT 5043
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
READ 50 GHZ BAND TO
MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 283308 WAS TESTED

AND FOUND TO OSCILLATE AT 5040

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024
TUNING FORK SERIAL NUMBER 964230 WAS TESTED
AND FOUND TO OSCILLATE AT 5040 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO
READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 964247 WAS TESTED

AND FOUND TO OSCILLATE AT 5044 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO

READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 020027 WAS TESTED

AND FOUND TO OSCILLATE AT 5046 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO

READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024
TUNING FORK SERIAL NUMBER 489832 WAS TESTED
AND FOUND TO OSCILLATE AT 5042 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO
READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 964251 WAS TESTED

AND FOUND TO OSCILLATE AT 5042 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO

READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 77632 WAS TESTED

AND FOUND TO OSCILLATE AT 5039

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED




TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024
TUNING FORK SERIAL NUMBER 020036 WAS TESTED
AND FOUND TO OSCILLATE AT 5045 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO
READ 50 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 010007 WAS TESTED

AND FOUND TO OSCILLATE AT 2021

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 283248 WAS TESTED

AND FOUND TO OSCILLATE AT 2016

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 964200 WAS TESTED

AND FOUND TO OSCILLATE AT 2017

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 964213 WAS TESTED

AND FOUND TO OSCILLATE AT 2017

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024
TUNING FORK SERIAL NUMBER 010008 WAS TESTED
AND FOUND TO OSCILLATE AT 2019 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 GHZ BAND TO
READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 010040 WAS TESTED

AND FOUND TO OSCILLATE AT 2017

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 964194 WAS TESTED

AND FOUND TO OSCILLATE AT 2016

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 77459 WAS TESTED

AND FOUND TO OSCILLATE AT 2016

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED 

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON March 12, 2024

TUNING FORK SERIAL NUMBER 010021 WAS TESTED

AND FOUND TO OSCILLATE AT 2017

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 33.800 CYCLES PER SECOND.
GHZ BAND TO

READ 20 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED

