TUNING FORK Certificate of Accuracy February 24, 2025

THIS IS TO CERTIFY THAT ON	February 24, 2025)	
TUNING FORK SERIAL NUMBER_	1504-138		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DO	3959 OPPLER RADAR OPERATION	IG IN THE 24.150	CYCLES PER SECOND. GHZ BAND TO
READ55		MPH.	1 1 11
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	4	Musliff

THIS IS TO CERTIFY THAT ON	February 24, 2025	120	
TUNING FORK SERIAL NUMBER_	180417		WAS TESTED
AND FOUND TO OSCILLATE AT _	2616	24.700	CYCLES PER SECOND
SUCH OSCILLATION CAUSES A D	OPPLER RADAR OPERATING IN TH	HE 34.700	GHZ BAND TO
READ25		_ MPH.	1 11/1
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	d	Mulling

THIS IS TO CER	TIFY THAT ON	February 24, 2025	5	
TUNING FORK S	SERIAL NUMBER	154628		WAS TESTED
AND FOUND TO	OSCILLATE AT	2616		CYCLES PER SECOND.
SUCH OSCILLAT	TION CAUSES A DOI	PLER RADAR OPERATING	IN THE 34.700	GHZ BAND TO
READ	25		MPH.	1.11
R & R RADA	HORSE PIKE	SIGNED	a	Mulling

THIS IS TO CERTIFY THAT ON	February 24, 2025		
TUNING FORK SERIAL NUMB	ER 127597		WAS TESTED
AND FOUND TO OSCILLATE A	AT	HE 34.7	CYCLES PER SECOND. GHZ BAND TO
READ25		MPH.	0 1
R & R RADAR, INC. 762 WHITE HORSE PIK ATCO, N.J. 08004	E SIGNED		A Missingly

THIS IS TO CERTIFY THAT ON	February 24, 2025				
TUNING FORK SERIAL NUMBER_	284234			WAS TESTED	
AND FOUND TO OSCILLATE AT	4167			CYCLES PER SECOND.	
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATING	IN THE	34.700	GHZ BAND TO	
READ40		MPH.		1.11	1
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		as	Musling	

THIS IS TO CERTIFY THAT ON	February 24, 2025		±*		
TUNING FORK SERIAL NUMBER	254060				WAS TESTED
AND FOUND TO OSCILLATE ATSUCH OSCILLATION CAUSES A DOP	4168	TUE	34.700		PER SECOND. GHZ BAND TO
READ40	FLER NADAN OPENATING IN	MPH.	2 117 00		GHZ BAND TO
R & R RADAR, INC. 762 WHITE HORSE PIKE	SIGNED		a	Ma	Delrff

THIS IS TO CERTIFY THAT ON	February 24, 202	25		
TUNING FORK SERIAL NUMBER	231155		+	WAS TESTED
AND FOUND TO OSCILLATE AT	4166			CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOI	PPLER RADAR OPERATING	G IN THE	34.700	GHZ BAND TO
READ40		MPH.		0.1/11
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	- 2	0	Musling

THIS IS TO CERTIFY THAT ON	February 24, 20)25	
TUNING FORK SERIAL NUMBER	020023		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOP	5043 PPLER RADAR OPERATII	NG IN THE33,80(_ CYCLES PER SECOND.) GHZ BAND TO
READ50	. 9	MPH.	1.11
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	d	Missinf

THIS IS TO CERT	IFY THAT ON	February 24, 20	25		
TUNING FORK SE	ERIAL NUMBER	020037			WAS TESTED
	OSCILLATE AT ON CAUSES A DOF	5044 PLER RADAR OPERATIN	IG IN THE3	CYCLE	S PER SECOND. _ GHZ BAND TO
READ	50		MPH.	A JAN	INII. IL
R & R RADA 762 WHITE H ATCO, N.J. 08	ORSE PIKE	SIGNED	- 44 w	CX / / h	ex wiff

THIS IS TO CER	TIFY THAT ON	February 24, 202	25			
TUNING FORK S	SERIAL NUMBER	964200				_WAS TESTED
AND FOUND TO	OSCILLATE AT	2016			CYCLES	PER SECOND.
SUCH OSCILLAT	TON CAUSES A DO	PPLER RADAR OPERATIN	GINTHE	33.800		GHZ BAND TO
READ	20	,	MPH.		1	11/11/
R & R RADA	HORSE PIKE	SIGNED		2	1///	Denff

THIS IS TO CERTIFY THAT ON		
TUNING FORK SERIAL NUMBER		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOPP		CYCLES PER SECOND.
READ	MP	н Д. / //
R & R RADAR, INC. 762 WHITE HORSE PIKE	SIGNED	S Midlings

THIS IS TO CERTIFY THAT ON	February 24, 20	25	· · · · · · · · · · · · · · · · · · ·
TUNING FORK SERIAL NUMBER	010008		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOPF			CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	1 . 1 1/
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	all	Misserff

THIS IS TO CERTIFY THAT ON	February 24, 2025		
TUNING FORK SERIAL NUMBER _	245663		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DO	2016 OPPLER RADAR OPERATING IN THI	E33.800	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	Dest 11
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	a	Mulling

THIS IS TO CERTIFY THAT ON	February 24, 20	25	
TUNING FORK SERIAL NUMBER			WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOPPLI			CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		 -

THIS IS TO CERTIFY THAT ON	February 24, 2025		,
TUNING FORK SERIAL NUMBER	245658		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOP		E33.800	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	1.11
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	a	Milling

THIS IS TO CERTIFY THAT ON	February 24, 202	25	
TUNING FORK SERIAL NUMBER	010020		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOR		G IN THE33.80	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	0.111
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	a	Madeliff

THIS IS TO CERTIFY	THAT ON	February 24, 202	5	-				_
TUNING FORK SERIA	L NUMBER	77459				WAST	ESTE	D
AND FOUND TO OSC	ILLATE AT	2016			CYCLES	PER SE	CONE).
SUCH OSCILLATION	CAUSES A DOF	PPLER RADAR OPERATING	IN THE	33.800		GHZ BA	ND T	С
READ	20		MPH.		1		1	1

R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004

SIGNED

THIS IS TO CERTIFY THAT ON	February 24, 202	25	
TUNING FORK SERIAL NUMBER	010007		WAS TESTED
AND FOUND TO OSCILLATE AT			CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATIN	G IN THE33.8	00 GHZ BAND TO
READ		MPH.	Darlal Il
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	a	Musery

THIS IS TO CERTIFY THAT ON	February 24, 2025	
TUNING FORK SERIAL NUMBER	467384	WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOF		CYCLES PER SECOND. GHZ BAND TO
READ	N	APH.
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	astructuff

THIS IS TO CERTIFY THAT ON	February 24, 2025			
TUNING FORK SERIAL NUMBER	283248			WAS TESTED
AND FOUND TO OSCILLATE AT	2015			CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOP	PPLER RADAR OPERATING II	NTHE	33.800	GHZ BAND TO
READ		MPH.		DAMMI II
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		00	Musery

THIS IS TO CERTIFY THAT ON	February 24, 20)25		
TUNING FORK SERIAL NUMBER	964213			WAS TESTED
AND FOUND TO OSCILLATE AT			CYC	LES PER SECOND.
SUCH OSCILLATION CAUSES A DOP	PLER RADAR OPERATII	NG IN THE	33.800	GHZ BAND TO
READ		MPH.	1	11/1/1/1/
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		Wille	Went

THIS IS TO CERTIFY THAT ON	February 24, 2025		
TUNING FORK SERIAL NUMBER	010021		WAS TESTED
AND FOUND TO OSCILLATE AT	2018		CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATING I	N THE	33.800 GHZ BAND TO
READ		MPH.	ne March
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		Winney

THIS IS TO CERTIFY THAT ON	February 24, 2025		
TUNING FORK SERIAL NUMBER	010040		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOP	2018 PLER RADAR OPERATING IN	THE33.	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	0.10
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		Maling

THIS IS TO CERTIFY THAT ON	February 24, 2025		¥.	
TUNING FORK SERIAL NUMBER	964194			WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DO		THE	33.800	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.		0 1 .
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		d	Mary

THIS IS TO CERTIF	Y THAT ON	February 24, 202	25	
TUNING FORK SEF	RIAL NUMBER	020027		WAS TESTED
AND FOUND TO OS	SCILLATE AT	5047		CYCLES PER SECOND.
SUCH OSCILLATIO	N CAUSES A DOF	PPLER RADAR OPERATIN	G IN THE33.8	00 GHZ BAND O
READ	50	,	MPH.	Jana all
R & R RADAR 762 WHITE HO		SIGNED		Willen

@ G085 4418

ATCO, N.J. 08004

THIS IS TO CERTIFY THAT ON	February 24, 2025	
TUNING FORK SERIAL NUMBER	964230	WAS TESTED
AND FOUND TO OSCILLATE AT	5038	CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATING IN THE _	33.800 GHZ BAND TO
READ	MP	
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	althulloff

THIS IS TO CERTIFY THAT ON	February 24, 202	5		
TUNING FORK SERIAL NUMBER	245686		0	WAS TESTED
AND FOUND TO OSCILLATE AT	5041		CYCL	ES PER SECOND.
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATING	IN THE	33.800	GHZ BAND TO
READ50		MPH.	1	11/11/11/
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		alle	USUNF

THIS IS TO CERTIFY THAT ON February 24, 2025 TUNING FORK SERIAL NUMBER ___ 77632 WAS TESTED AND FOUND TO OSCILLATE AT ___ 5043 CYCLES PER SECOND. SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE _ 33.800 R & R RADAR, INC.

SIGNED

762 WHITE HORSE PIKE ATCO, N.J. 08004

THIS IS TO CERTIFY THAT ON	February 24, 2025	,	
TUNING FORK SERIAL NUMBER	467355		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DOF	5041 PPLER RADAR OPERATING	IN THE33.80	CYCLES PER SECOND. GHZ BAND TO
READ		MPH.	1 111
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	4	Mulling

THIS IS TO CERTIFY THAT ON	February 24, 2025			
TUNING FORK SERIAL NUMBER	283308			WAS TESTED
AND FOUND TO OSCILLATE AT	5039		CYC	LES PER SECOND.
SUCH OSCILLATION CAUSES A DOF	PLER RADAR OPERATING I	NTHE	33.800	GHZ BAND TO
READ	*	MPH.	Da	alal II
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		Win	wing

THIS IS TO CERTIFY THAT ON	February 24, 20	25	
TUNING FORK SERIAL NUMBER	964247		WAS TESTED
AND FOUND TO OSCILLATE AT	5043	*	CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOP	PLER RADAR OPERATIN	IG IN THE33.800	GHZ BAND TO
READ		MPH.	Dariel II
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	W	Trustry

THIS IS TO CERTIFY THAT ON	February 24, 2025	
TUNING FORK SERIAL NUMBER _	020036	WAS TESTED
AND FOUND TO OSCILLATE AT	5045	CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DO	PPLER RADAR OPERATING IN THE	33.800 GHZ BAND TO
READ		MPH. Dans I
R & R RADAR, INC.		Whatlings
762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	

@ Goes 4418

ATCO, N.J. 08004

THIS IS TO CERTIFY THAT ON	February 24, 2025		
TUNING FORK SERIAL NUMBER _	49244		WAS TESTED
AND FOUND TO OSCILLATE AT SUCH OSCILLATION CAUSES A DO READ	AUTT-	NTHE	CYCLES PER SECOND. GHZ BAND TO
35		IVIETI.	MARINII IV
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED	a	VII WARE